




J1

+12V



UI




J3

Fasten 2




X1

4MHz



J2

Fasten



J5

ICP

